ICF TECHNOLOGY

SITE SAFETY PLAN

A. GENERAL INFORMATION

Project Title: Touchstone Propert Location(s): Hackberry, Louisian Project Manager: Prepared (SSO): Approval (RHSO):				PAN: TDD No.:	ILA0154XAA F-6-9001-8	6-9001-8	
				EPA ID No.: Project Dir.: Date Prepared: Date Approved:	/ LAD981910706 / Steve Cowan 9/21/90		
	(CHSO): _ Objective of V	Vork: <u>To perfor</u>	rm a Listing Site Inspection san	Date Approved: npling mission of Tou	ochstone Properties.		
Proposed	Date of Fiel	d Activities:	September 23-28,1990			· · · · · · · · · · · · · · · · · · ·	
Backgrou	nd Informati	on:	Complete [X]	Preliminary (no analytical [] data available)			
Documen	tation / Sum	mary:					
	Overall Che	emical Hazard:	Serious [] Low [X]	Moderate [X] Unknown []			
	Overall Phy	sical Hazard:	Serious [] Low [X]	Moderate [] Unknown []			
			B. SITE / WA	STE CHARACTERIS	STICS		
Waste Ty	pe(s):						
	Liquid	[X]	Solid []	Sludge []	Gas/Vapor	[X]	
Character	ristic(s):						
	Flammable/ Ignitable	[X]	Volatile [X]	Corrosive []	Acutely Toxic	[X]	
	Explosive	[]	Reactive []	Carcinogen []	Radioactive	1.1	
	Other: _						
Dhaminal I	Id						
Physical I				_			
	Overhead	[]	Confined [] Space	Below [] Grade	Trip/Fall	[X]	
	Puncture	[]	Burn []	Cut []	Splash	[X]	
	Noise	[]	Other: Heat Stress precaution:	s will be in place.	· · · · · · · · · · · · · · · · · · ·		

Requires completion of additional form and special approval from the Corporate health / Safety group. Contact RSC or HQ.



90069289

Site History / Description and Unusual Feature, . Sampling Plan for detailed description): Touchstone Properties, an inactive oil field waste disposal site, is located in Hackberry, Cameron Parish, Louisiana, approximately 1.000 feet east of 1.A Hwy 27 and 2,500 feet west of the Calcasieu Ship Channel. The site consists of two pits. The site is bordered on the north, west and south by an adjacent drainage ditch and Pete Seay Circle Road. Adjacent to the east side of the site is a surface water pond. Touchstone Properties, which leases the property for oil and gas exploration, claims the site is inactive and no longer used for oil field waste disposal. The site is accessible to the public, so the potential exists for midnight dumping. It is not clear who owns the property. Locations of Chemicals / Wastes: Any oil field waste would be located in the two on-site pits. Estimated Volume of Chemicals / Wastes: The volume of waste can not be evaluated because the dimensions of the pits are not known. Site Currently in Operation Yes [] No [X] C. HAZARD EVALUATION List Hazards by Task (i.e., drum sampling, drilling, etc.) and number these. (Task numbers are cross-referenced in Section D) Physical Hazard Evaluation: Task 1: Drinking Water Well Sampling.

Chemical Hazard Evaluation:

Task 2: Task 3: Surface Water/Sediment Sampling.

Surface Soil Sampling.

COMPOUND		ROUTE OF EXPOSURE	ACUTE SYMPTOMS	ODOR THRESHOLD	ODOR DESCRIPTION
Barium	0.5 my ling	inhalis	tion upper	respirati	TI VANS
Chreinian	1 my lin 3	;	nasa)	exptini	+ incres
2/10	Jary la 3	: 1		rit me th	1111
Bonzene Chlomborn	1 ppm	,,	dizz me	11/	not Arometic
Ethylbenzene	20 ppm	′1	intege	·	& Aronstic
Vilenes	4000pm	,,,	ftg, we	ak, confi	and Around
Naph thalenes	100ppin	//	oye IVI	t. hord sil	f mothers
	· ·				

NOTE: Complete and attach a Hazard Evaluation Sheet for major known contaminant.

D. SITE SAFETY WORK PLAN

Site Control: Attach map or sketch of site showing hot zone, contamination reduction zone, etc.

Perimeter identified? [XX] Site secured? [XX]
Work areas designated? [XX]
Zone(s) of contamination identified? [XX]

Personal Protection (TLD badges required for all field personnel):

Anticipated Level of Protection (Cross-reference task numbers to Section C):

	А	D	C	D
Task 1				xxx
Task 2				xxx
Task 3		-	xxx	xxx
Task 4				

(Expand if necessary)

Modifications: Task 2 (Surface Water/Sediment Sampling) will include splash protection.

Action Levels for Evacuation of Work Zone Pending Reassessment of Conditions:

- Level D: Organic vapors above background levels (HNu 10.2 probe)
 RAM-4 > 0.1 mR/hr.
- Level C: Unknown organic vapors (in breathing zone) > 5 ppm, RAM-4 . 0.1 mR/hr.

Level B and Level A will not be used during this sampling mission. If level B is necessary, the FIT will return to Dallas to gather appropriate gear.

Air Monitoring (daily calibration unless otherwise noted)

Contaminant of Interest	Type of Sample	Menitoring	Frequency
Barium, Chromium, Lead, Zinc.	area	PDM-3	continuous
Benzene, Chloroform, Ethylbenzene,	personal	HNu 10.2 probe	continuous
Toluene, Xylenes, Napthalenes.	personal	HNu 10.2 probe	continuous
			,

(Expand if necessary)

Personnel Decontamination Protocol:	a trisodium phosphota (TSP)/Detergent solution, through a tan water rises
and through a final rinse. PPE will then be removed and disposed of appropri	a trisodium phosphate (TSP)/Detergent solution, through a tap water rinse
the CRZ to assist the FIT in the decon procedures. Once the procedures are	complete, the personnel may enter the Support Area.
	· ·
Decontamination Solution Monitoring Procedures, if applicable: HNu	(10.2 probe) will be used to monitor the decon solution.
Special Site Equipment, Facilities, or Procedures (Sanitary Facilities and Ligh	ting Must Meet 29 CFR 1910.120):
Sanitary facilities will be located once on-site. FIT will work only during dayle	ight hours to comply with lighting requirements.
	ite using the monitoring instruments prior to on-site work. If action levels are
within required standards, the FIT will begin work.	
	
Work Limitations (time of day, weather conditions, etc.) and Heat / Cold Stre	
Work will proceed only during the daylight hours. Heat Stress symptoms will Frequent breaks will be taken to avoid heat exhaustion.	be closely monitored.
Treductive oreate with the taken to avoid meat annualities.	
General Spill Control, if applicable: N/A	· · · · · · · · · · · · · · · · · · ·
Investigation-Derived Material Disposal (i.e., expendables, decon waste, cuttin	
PPE will be decontaminated, double-bagged and disposed in a RCRA D land! IDW will be handled according to the IDW SOP.	
117W WIII DE HAIIGICU ACCORDING TO THE 115W 301.	
Sample Handling Procedures including Protective Wear:	
Surgies and splash protection will be worn by personnel preserving water samp	ples.
	•
Team Member	Responsibility
Steve Cowan	Team Leader
Don Hudnall	Site Safety Officer
Kevin Jaynes	
Warren Mitchell	
Nancy Roberts Pakert Traffa	
Robert Taaffe Trudy Tannen	
Treat Tainell	

[&]quot;All entries into exclusion zone require Buddy System use. All E & E field staff participate in a medical monitoring program and have completed applicable training per 29 CFR 1910.120. Respiratory protection program meets requirements of 29 CFR 1910.134, and ANSI Z88.2 (1980).

E. EMERGENCY INFORMATION

(Use supplemental sheets, if necessary)

LOCAL RESOURCES

Ambulance:	Ambulance Service of West Calcasieu Cameron	318/527-8322
Hospital Emergency Room:	West Calcasieu Cameron	318/527-7034
Poison Control Center:	Galveston County Regional	409/761-1420
Police (local/county/state):	Cameron Parish	318/433-3431
Fire Department:	Hackberry Fire Department	318/762-4777
Airport:	Lake Charles Municipal Airport	318/477-6051
Agency Contact (EPA/State)		
Local Laboratory:		
Federal Express:	1-800-238-5355	
Client/EPA Contact:		
Site Contact:		

SITE RESOURCES

1	Site Emergency Evacuation Alarm Method:	Warnings will be announced through walkie talkies, car horns or shouting.
1	Water Supply Source:	Potable will be brought on-site by the FIT.
Į.	Telephone Location & Number:	
1	Cellular Phone, if available:	
	Radio:	EPA dedicated radios will be used to keep in touch with downrange teams.
i	Other:	

EMERGENCY CONTACTS

(E & E)

1.	Dr. Raymond Harbison	(Univ. of Florida)501/221-0465 or 904/462-3277.3281 Alachua, Florida501/370-8263 (24 hours)
2.	Ecology and Environment, I Paul Jonmaire E & Es Safety Officer	nc., Safety Director716/684-8060 (office)214/742-6601 (office)
3.	FITOM K.H. Malone, Jr.	214/742-6601 (office) 214/867-8073 (home)
	TATOM Kishor Fruitwala	214/742-6601 (office) 817/274-8073 (home)
	AFITOM John R. Totin	214/742-6601 (office) 214/424-3791 (home)

MEDTOX HOTLINE

1.	Twenty-four hour answering service:		501/370	501/370-8263				
	What to	report:	State: "] • • •	This is an emergency. Your name, region Telephone number Your location. Name of person in Nature of emerger Action time.	n and site. r to reach you. njured or exposed.			
2.	A toxico	ologist (Dr. Raymond Harbison	or associa	te) will contact you.	Repeat the informa	tion given to the answering service.		
3.	If a toxi	cologist does not return your ca	all within 1	5 minutes, call the fo	ollowing persons, in	order, until contact is made:		
	A. B. C.	24 hour hotline Corporate Safety Director Assistant Corporate Safety C	Officer	Paul Jonmaire Steven Sherman	(home phone) (home phone)	716/684-8940 716/655-1260 716/688-0084		
				EMERGENCY	ROUTES			
		(NC	OTE: <u>Field</u>	Team Must Know R	oute(s) Prior to Star	t of Work)		
		pital (include map):	get to Calc	osieu Marine Park ta	ske a left. Vou will	come to Y in the road. Stay to the rig	aht.	
		Cypress Street. The hospital w						
		-						
Emerge	Emergency Egress Routes to Get Off-Site: Will be determined upon arrival at the site.							
	· •							
								
					·			

ICF TECHNOLOGY, INC.

SITE SAFETY PLAN ATTACHMENT

Emergency Procedures

1. If a person exposed to hazardous materia via:

Skin:

Compound-specific. See attached HED.

Inhalation:

Compound specific. See attached HED.

Ingestion:

Compound specific. See attached HED.

2. If person injured:

Remove victim from dangerous area and administer first aid. Transport victim to hospital if necessary. Notify Dallas office at (214) 744-1641, and Jerry Joy at (412) 788-9200 or at his beeper number.

3. If potential or actual fire or explosion:

Evacuate the endangered area. Administer first aid and seek medical attention, if necessary. Notify local emergency response personnel. Contact the Dallas office at (214) 744-1641, and Jerry Joy at (412) 788-9200 or at his beeper number.

4. If radiation exposure:

Evacuate site. Take victim to hospital. Notify the Dallas office at (214) 744-1641, and Jerry Joy at (412) 788-9200 or at his beeper number.

5. If contaminant spreads beyond site:

Evacuate site. Administer first aid and seek medical attention if necessary. Notify local emergency response personnel. Contact the Dallas office at (214) 744-1641, and Jerry Joy at (412) 788-9200 or at his beeper number.

6. Procedures for inclement weather:

Wait for weather to clear.

EMERGENCY CONTACTS

Regional Health and Safety Manager: Don L. Hudnall (214) 744-1641

. (817) 460-3363

Project Manager: Debra Pandak (214) 744-1641

Corporate Health and Safety Officer: Jerry Joy (412) 788-9200

— or —

Jerry's Beeper:

- 1. 1-800-443-7243
- 2. Enter 062438 (IC Code)
- 3. At the tone, enter phone number to be called; press # (pound).
- 4. At the tone, press # (pound) again and hang up.
- 5. Wait for Jerry to call back.

ICF TECHNOLOGY, INC.

SITE SAFETY ATTACHMENT

ACCIDENTS IN THE FIELD

If you have an automobile accident while on the job, you need to know the following:

- 1. ICF INSURANCE CARRIER Johnson & Higgins, Washington, D.C.
- 2. INSURANCE CARRIER CONTACT Mr. Sal Perrucci (202) 775-1900
- 3. ICF LEGAL / INSURANCE CONTACT -
 - A. Joseph Balac (703) 934-3350 (Primary Contact)
 - B. Philip Kessack (703) 934-3964 (Secondary Contact if Joseph Balac is unavailable)

If you are injured on the job, you are covered by Texas Worker's Compensation. Do <u>NOT</u> use your Blue Cross/Blue Shield; instead, provide the following information for treatment:

- 1. WORKER'S COMP CARRIER AND IDENTIFICATION NUMBER AIAC, Policy No. WC 1907869
- 2. ICF WORKER'S COMP CONTACT -Sheryl Summa (703) 934-3587

Several important reminders:

- 1. Call Insurance and ICF contacts (including Dallas office) ASAP.
- 2. Do not make any statements concerning liability or fault.
- 3. As soon as you can, re-think the events of the accident <u>on paper</u> e.g., when, where, how, why, witnesses, damages, injuries, license numbers (for auto accidents), etc.